

SAFETY ALERT

URS Washington Division
 Brandon Shores AQCS Project Safety

PRODUCT DEFECT



Capital Safety (Protecta) 6' wire rope cable for fall protection anchorage



Properly crimped fittings at one end.

Fittings at other end not crimped.



Wire rope pulls free of fittings with minimal force applied.

This 6' Capital Safety- (Protecta) anchorage connector for fall protection was found by one of our Ironworkers during his pre-use PPE inspection.

Two have been found to be defective from the factory:

Mfg 08/JUN

LOT# 13756017

Model# AJ408AG

Length# G 6

The eye in the wire rope, formed with the connectors which are crimped, pulled loose during the inspection. This obviously renders it completely ineffective.

We suggest pulling all of these from use and storage immediately and inspecting them.

We have notified the vendor and are waiting for further instructions once he makes contact with the manufacturer.