

## How can you safely work near moving/energized parts?

[Ask the following questions and give time for answers.]

What are the hazards? Bodily contact with moving and energized parts, potential and stored energy

What are the results? Broken or crushed limbs and bones, suffocation, punctures, head injury, internal damage, amputations and death

What should we look for? Machine guards, moving and energized parts, nip-points, lockout/tagout, loose/hanging clothing, jewelry and hair

## [Relate this incident or one you know.]

**Actual Incident:** On January 26th, 2005 a 43-year-old male city DPW sanitation worker was killed when his sweatshirt became entangled around an unguarded Power Take Off (PTO) shaft on a salt truck. The DPW mechanical crew repaired the bed chain on the vehicle prior to the incident but returned the truck to service without installing the shaft guard that covered the PTO shaft. It appeared that when the victim walked to the rear of the truck to check the salt spreader, his orange safety sweatshirt was caught by the rotating shaft stub. The victim was found entangled by a co-worker and transported to a hospital by EMS where he was pronounced dead.


## [Ask the following question and ensure every item is covered.] How do we prevent these results?


- □ Service equipment following manufacturer's instructions.
- Only use equipment when manufacurer's guards or an adequate replacement guard is in place and operational.
- □ Inspect all safety guards before operating equipment.
- Never remove machine guards while equipment is energized or can potentially become energized.
- □ Never alter machine guards without manufacturer's approval.
- De-energize and lock-out equipment's energy before removing guard to service equipment. Always replace guards after servicing equipment.
- Don't wear loose clothing, jewelry and keep hair tight when operating.

[Ask the following questions about this site and ensure every item is covered.] \_\_\_\_\_ Let's talk about this site now.

- □ How can you prevent accidental contact with energized equipment and moving parts? *Guard moving and energized parts or lockout/tagout.*
- □ What should you do if you notice a missing or broken/altered guard? Do not use equipment, shut it down when it is safe to do so and inform supervisor of danger.
- Does your company have a machine guarding safety program; have you read it?

[Record questions below that you want to ask about this site.] =





## IUOE National Training Fund • 304.253.8674 • www.iuoeiettc.org

This material was produced under grant number SH-16591-07-06-F-11 from the Occupational Safety and Health Administration, U.S. Department of Labor. It does not necessarily reflect the views or policies of the U.S. Department of Labor, nor does mention of trade names, commercial products, or organizations imply endorsement by the U.S. Government.